

**FILARTEX**  
Y A R N S   E V E R Y   W E A R

**SPICY BOX**

# PRODUCTION PROGRAMME

## FRESCO

100% Gassed ELS Cotton - Ne 60/3= Nm 3/100;  
Stock Service Shades •

## FRESCHISSIMO

100% Gassed ELS Cotton - Ne 60/4 = Nm 4/100;  
Stock Service Shades #

## GALASSIA CRÈPE

100% Crèpe Combed Cotton  
Ne 30/2= Nm 2/50; Stock Service Shades ■  
Ne 30/3= Nm 3/50; Stock Service Shades ■

## SHARP

100% Gassed ELS Cotton - Ne 1,9 = Nm 3300;  
Stock Service Shades ••

## POLYCORE

75% ELS Cotton - 25% Elité 56 Dtex - Ne 60/2= Nm 2/100;  
Stock Service Shades ▲

## ALLURE

50% Cotton - 50% Crèpe Viscose - Ne 30/2= Nm 2/50;  
Stock Service Shades \*

### CARE INSTRUCTIONS



## FRESCO

100% Cotone ELS Gasato - Ne 60/3 = Nm 3/100;  
Colori stock service •

## FRESCHISSIMO

100% Cotone ELS Gasato - Ne 60/4 = Nm 4/100;  
Colori stock service #

## GALASSIA CRÈPE

100% Cotone Pettinato Crèpe  
Ne 30/2= Nm 2/50; Colori stock service ■  
Ne 30/3= Nm 3/50; Colori stock service ■

## SHARP

100% Cotone ELS Gasato - Ne 1,9 = Nm 3300;  
Colori stock service ••

## POLYCORE

75% Cotone ELS - 25% Elité 56 Dtex - Ne 60/2= Nm 2/100  
Colori stock service ▲

## ALLURE

50% Cotone - 50% Viscosa Crèpe - Ne 30/2= Nm 2/50  
Colori stock service \*

### SIMBOLI DI MANUTENZIONE















---

## FILARTEX

Via Firenze, 13 - I-25036 Palazzolo s/O (BS)  
Tel. +39 030.7401612 - Fax +39 030.7401661  
[www.filartex.it](http://www.filartex.it)  
Italia: [filati@filartex.it](mailto:filati@filartex.it) - Worldwide: [yarns@filartex.it](mailto:yarns@filartex.it)



**USTERIZED®**