

**FILARTEX**  
Y A R N S   E V E R Y   W E A R

**WASH OUT**

# PRODUCTION PROGRAMME

## WASH OUT

100% Cotone - Ne 30/2 = Nm 2/50  
Colori stock service •

### ISTRUZIONI DI LAVORAZIONE

La stabilità dimensionale e l'aspetto del capo saranno ottimali solo in seguito al primo lavaggio in acqua con sapone neutro. La venditrice non si assumerà nessuna responsabilità per contestazioni derivate da difettosità o incognite del prodotto, che comunque fossero già presenti nel filato campionato. E' quindi indispensabile che l'utilizzatore del filato esegua accurati test in fase di campionatura. Non si accettano reclami per quantitativi di tessuto superiore a Kg. 5 per ogni bagno di tintura, in nessun caso capi confezionati. E' consigliato operare a 2 o più guidafile, soprattutto in caso di punti rasato e maglia unita, unitamente a dispositivi per il controllo dell'alimentazione. Per le caratteristiche del prodotto uno scarto del 5% è da considerarsi nei costi di tessitura. Raccomandiamo controllare attentamente i teli durante il processo di tessitura e di interrompere immediatamente la lavorazione in caso di evidenti irregolarità.

### SIMBOLI DI MANUTENZIONE



## WASH OUT

100% Cotton - Ne 30/2 = Nm 2/50  
Stock Service Shades •

### MANUFACTURING INSTRUCTIONS

The size stability and the final aspect of the garment will be only settled after the first washing with water and neutral soap. The seller will not assume any responsibility for claims arising from defects or unknown factors of the product, which anyway were already present in the yarn sampled. It is then essential that the yarn buyer proceeds with trials during the sampling phase. Claims for fabric quantities higher than 5kg per dyeing lot will absolutely not be accepted, and in anyway absolutely not for ready garments. It's advisable to work with 2 or more thread guides, especially in case of plain-knitted and full needle stitch, combining also devices for the feeding control. Due to product final characteristics, a waste of 5% is to be considered on knitting costs. We strongly advise a quality control on panels during the knitting phase, process to be interrupted immediately in case of any irregularity.

### CARE INSTRUCTIONS







---

**FILARTEX**

Via Firenze, 13 - I-25036 Palazzolo s/O (BS)  
Tel. +39 030.7401612 - Fax +39 030.7401661  
[www.filartex.it](http://www.filartex.it)  
Italia: [filati@filartex.it](mailto:filati@filartex.it) - Worldwide: [yarns@filartex.it](mailto:yarns@filartex.it)